

Classification:

Reference:

COPYRIGHT © NISSAN NORTH AMERICA, INC.

Date:

EC10-018

ITB10-039

June 21, 2010

## MIL "ON" WITH DTC P0128 (THERMOSTAT FUNCTION) STORED

**APPLIED VEHICLES:** 2002 and later Infiniti vehicles

### IF YOU CONFIRM

The MIL is "ON" with P0128 (Thermostat Function) stored.

### ACTIONS

1. Check to see if an aftermarket remote starter system is installed.
  - Remote starter systems may cause the MIL to illuminate and DTC P0128 to store.
2. If a remote starter system is installed, remove/disconnect it before performing diagnostic procedures on the vehicle.
3. Refer to ASIST and the Electronic Service Manual (ESM) for diagnostic information.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti dealer to determine if this applies to your vehicle.