

Classification:

EL08-034

Reference:

ITB08-052

COPYRIGHT© NISSAN NORTH AMERICA, INC.

Date:

December 15, 2008

## INFINITI; I-KEY REGISTRATION CAUTION

**APPLIED VEHICLES:** All Models with Intelligent Key (I-Key)

**CAUTION:** Before starting **any** I-Key registration procedures:

- #1: The vehicle battery voltage **must be** at and remain above 12.4 volts during the procedure.

**THEN**

- #2: The transmission selector lever **must be** in the Park position for A/T vehicles or in the Neutral position for Manual transmission vehicles.

**THEN**

- #3: "Wiggle" the steering wheel back and forth to make sure the steering lock is not bound-up on the column, and then release the Steering Lock.

**THEN**

- #4: Proceed with I-Key registration.

**If these steps are not followed before I-Key registration is started electronic damage to the Steering Lock may occur.**

Electronic damage to the Steering Lock is not covered under warranty if it should occur under these conditions.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.