

**Classification:**

EL09-015

**Reference:**

ITB09-022

COPYRIGHT © NISSAN NORTH AMERICA, INC.

**Date:**

April 27, 2009

## IPDM SERVICE


**APPLIED VEHICLES:** 2007 - 2009 Infiniti Models with IPDM

### SERVICE INFORMATION

The Intelligent Power Distribution Module (IPDM) is **ONLY** serviceable as an assembly.

The **ONLY** serviceable parts of an IPDM are the fuses.

- Some IPDM designs have sections that appear to be serviceable relays.
- These "relays" are **NEVER** to be removed.
- These "relays" may have markings indicating they are similar. They are not "swappable".



### CAUTION:

**NEVER REMOVE** relays from an IPDM.

Tampering with the relays of an IPDM may cause additional incidents with the vehicle. Such incidents may include:

- Headlights inoperative.
- Radiator fan inoperative
- Fog lamps inoperative
- Wiper inoperative

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti dealer to determine if this applies to your vehicle.