

Classification:
Reference:
Date:

WT08-006

ITB08-014

March 10, 2008

TPMS SENSOR SEAL LEAK




APPLIED VEHICLES: 2004 – 2006 G35 Sedan (V35) with TPMS
 2004 – 2007 G35 Coupe (CV35) with TPMS
 2004 – 2008 FX (S50) with TPMS
 2004 M45 (Y34) with TPMS
 2006 – 2008 M (Y50) with TPMS
 2004 – 2006 Q45 (F50) with TPMS
 2004 – 2008 QX56 (JA60) with TPMS

SERVICE INFORMATION

When repairing an air leak at a TPMS (Tire Pressure Monitor System) sensor seal, a seal is now available separately.

Do not replace the entire sensor when only a seal is needed.

PARTS INFORMATION

TPMS Sensor Part Number	Use Sensor Seal Part Number
40700-CK002 (Gray)	40702-CK002 
40700-CD001 (Blue) 40700-CK001 (Moss green)	40702-CD001 
40700-JA01B (Yellow) 40700-JA00B (Light Green) 40700-JA00C (Orange)	40702-JA01A 

CLAIMS INFORMATION

Reference the current Infiniti Warranty Flat Rate Manual for claims coding information.