

Classification:

Reference:

Date:

BR14-005

ITB14-044

September 3, 2014

REAR BRAKE SQUEAK NOISE

APPLIED VEHICLES: 2012-2014 EX35 and QX50 (J50)
 2012-2014 FX and QX70 (S51)
 2012-2014 M, M Hybrid, Q70, and Q70 Hybrid (Y51)
 2012-2013 G37 Sedan (V36)

IF YOU CONFIRM:

The rear brakes squeak when braking while the brakes are at normal operating temperature

AND

The applied vehicle is equipped with single piston rear brake calipers.

ACTION:

Replace the hardware on both rear brake calipers with the kit listed in **PARTS INFORMATION** below.

NOTE: Machining of the rotors is not necessary.

Refer to the Electronic Service Manual (ESM), section **BR-Brake System**, for removal and installation.

PARTS INFORMATION

DESCRIPTION	PART #	QUANTITY
HARDWARE KIT	D4080-9N00C	1

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
RPL Rear Brake Caliper Hardware – Both Sides	D4080-9N00C	PD19AA	DD	32	(2)

(1) Reference the current Infiniti Warranty Flat Rate Manual and use the indicated FRT.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.