

**Classification:**

FE08-002a

**Reference:**

ITB08-023a

**Date:**

November 24, 2009

## 2008 - 2009 G37 COUPE; RATTLE IN MAIN MUFFLER

This bulletin has been amended. The Applied Vehicles, VIN and Date, have been updated, and the Parts Information has been changed. Please discard earlier versions of this bulletin.

**APPLIED VEHICLE:** 2008 - 2009 G37 Coupe (CV36)

**APPLIED VIN:** 2008 all VINs  
 2009 vehicles built before JNKCV64(\*\*)9M 605009

**APPLIED DATE:** Vehicles built before February 26, 2009.

**IF YOU CONFIRM:**

There is a rattle sound coming from inside the main (rear) muffler assembly.

**ACTION:**

Replace the muffler assembly with the one listed in the Parts Information section of this bulletin.

- Reference the Electronic Service Manual for muffler replacement information.

**PARTS INFORMATION**

Description	Drive Type	PART number	Quantity
Muffler Assy – Exhaust Main	2WD	20100 – JL01C	1
	AWD	20100 – 1ND0B	
Gasket – Exhaust	2WD or AWD	20692 – 1E810	2

**CLAIMS INFORMATION**

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
RPL Main Muffler Assy	(1)	FD60AA	BC	32	(2)

- (1) Reference the Parts Information Table and use the applicable Muffler Assy – Exhaust Main P/N as the PFP.  
 (2) Reference the current Infiniti Warranty Flat Rate Manual and use the indicated FRT.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti dealer to determine if this applies to your vehicle.